

New Corena S - Possible Colour Change

- Red/pink oil discoloration was observed in some field applications
- Discoloration is due to the operation of the antioxidant
- No loss of performance is involved
- Over time the oil turns dark brown

